



RENAULT Kangoo Express: 1CSE132

Vinnnumber:	VF1FW15B546838992	Versionname:	KANGOO Expr. B/F PLC Gr.Conf.(EU5)90PK
First Registrationdate:	15/02/2012	Fiscalpower:	
Expertise Mileage:	116545	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1116
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1206,19
-------------------	----------------

Bumper R, Damaged, Smart repair	110,64
---------------------------------	---------------



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	---------------



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk door R R, Scratch(es), Acceptable 0,00

No pictures to display
Wheel cover R L, Missing, E - Replace 22,50



Door R R, Bump(s), PDR - Knock out without painting 63,00



Seat cover F L, Damaged, E - Replace 300,00



Door F R, Bump(s), Acceptable 0,00

No pictures to display
Roof pillar R, Bump(s), LI - Repair and paint (complete) 165,14



Bonnet, Bump(s), Acceptable 0,00

No pictures to display
Interior, Dirty, Cleaning 0,00



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Boot carpet, Damaged, E - Replace	75,00
-----------------------------------	-------

