


**TOYOTA Proace: 1GPE117**

Vinnumber:	<b>YARXTAHZ8DZ026039</b>	Versionname:	<b>PROACE B/F SWB Active</b>
First Registrationdate:	<b>24/03/2014</b>	Fiscalpower:	<b>128PK</b>
Expertise Mileage:	<b>127721</b>	Power Kw:	<b>94</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>2223</b>
Maintenance:	<b>-8400</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of Lining:	<b>Lining fabrics</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

215/60/16/103 T Steel				
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	431,79
Windscreen, Stone chip(s), Windscreen repair	0,00



Sliding door panel R, Hole, E - Replace	45,00
---	-------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

*No pictures to display*

Seat cover F L, Deformed, Acceptable	0,00
--------------------------------------	------



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), Smart repair 110,64



Sidewall panel FL, Hole, E - Replace 45,00



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15

