



**TOYOTA GRAND PRIUS+: 1NPK034**

Vinnnumber:	<b>JTDZS3EU40J007445</b>	Versionname:	<b>1.8 VVT-I HYBRID ACTIVE AUTO</b>
First Registrationdate:	<b>1/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>17223</b>	Power Kw:	<b>73</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>3604</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L
GPS storage	<b>HD</b>	Central consol F
GPS storage		Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting:	<b>Headlighting Halogen</b>	
Type of GPS:	<b>GPS big screen color</b>	
Type of Lining:	<b>Lining fabrics</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 6,5 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 8 mm</b>	Re.R.	<b>Bridgestone: 8 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	1659,83
Wheel cover F L, Missing, E - Replace	30,00



Maintenance book, Missing, E - Replace	0,00
--	------



Door panel R L, Scratch(es), E - Replace 114,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Instruction book, Missing, E - Replace 0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Front bumper, Broken, Le - Replace and paint 735,00



Bumper R, Scratch(es), Acceptable 0,00



Maintenance, Maintenance, Execute 0,00



Certificate Of Conformity, Missing, E - Replace 150,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F R, Scratch(es), Acceptable

0,00



Bumper grille, Broken, E - Replace

32,40



Centre console, Scratch(es), Smart repair

110,64



Bumper moulding R, Scratch(es), Acceptable

0,00

