



**RENAULT Scenic: 1EVQ313**

|                         |                          |              |                              |
|-------------------------|--------------------------|--------------|------------------------------|
| Vinnumber:              | <b>VF1JZ140648673954</b> | Versionname: | <b>SCENIC Energ.Business</b> |
| First Registrationdate: | <b>2/04/2013</b>         | Fiscalpower: | <b>110PK</b>                 |
| Expertise Mileage:      | <b>170587</b>            | Power Kw:    | <b>81</b>                    |
| Bodytype:               |                          | Body color:  | <b>Black</b>                 |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>               |
| Transmission:           |                          | Rims summer: | <b>Steel</b>                 |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                    |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>2514</b>                  |
| Number of doors:        | <b>5</b>                 |              |                              |
| Number of seats:        | <b>5</b>                 |              |                              |
| Number head rests:      | <b>5</b>                 |              |                              |
| Rims summer:            | <b>Steel</b>             |              |                              |
| Category:               | <b>Passenger Car</b>     |              |                              |
| Oil level:              | <b>OK</b>                |              |                              |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                    |       |                    |
|---------------|-----------------------------|--------------------|-------|--------------------|
|               | <b>205/60/16/96 H Steel</b> |                    |       |                    |
| Winter tyres: | Fr.L.                       | <b>Fulda: 3 mm</b> | Fr.R. | <b>Fulda: 3 mm</b> |
|               | Re.L.                       | <b>Fulda: 5 mm</b> | Re.R. | <b>Fulda: 5 mm</b> |

**Assistance equipment**

|             |            |
|-------------|------------|
| Spare wheel | <b>Yes</b> |
|-------------|------------|

|                   |                |
|-------------------|----------------|
| Total cost ex VAT | <b>1974,98</b> |
|-------------------|----------------|

|                                   |             |
|-----------------------------------|-------------|
| Door R L, Scratch(es), Acceptable | <b>0,00</b> |
|-----------------------------------|-------------|

*No pictures to display*

|   |               |
|---|---------------|
| Door F R, Scratch(es), LI - Repair and paint (complete) | <b>318,35</b> |
|---|---------------|



|                           |              |
|---------------------------|--------------|
| Interior, Dirty, Cleaning | <b>50,00</b> |
|---------------------------|--------------|



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R L, Scratch(es), It - Spot repair 115,56



Wheel cover F R, Scratch(es), E - Replace 30,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Bump(s), Smart repair 110,64



Door moulding Lower R R, Damaged, E - Replace 114,00



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

301,68

