



RENAULT Clio: 1GWL644

Vinnnumber:	VF15RJL0H50895035	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	20/05/2014	Fiscalpower:	
Expertise Mileage:	39433	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3812
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Winter tyres:	Fr.L.	Fulda: 6 mm	Fr.R.	Fulda: 6 mm
	Re.L.	Fulda: 6 mm	Re.R.	Fulda: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1086,68
Wheel cover F R, Damaged, E - Replace			24,00



Rearview mirror housing L, Scratch(es), Acceptable	0,00
---	-------------

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Wheel cover F L, Damaged, E - Replace 24,00



Wheel cover R L, Damaged, E - Replace 24,00



Boot carpet, Waterinfiltration, P - Check 0,00



Door R R, Accident, LI - Repair and paint (complete) 254,68



Wing R R, Accident, LI - Repair and paint (complete) 246,56



Wheel cover R R, Damaged, E - Replace 24,00



Rear window, Scratch(es), E - Replace 320,00



Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	