



## SEAT Alhambra: 1GDI318

Vinnnumber:	<b>VSSZZZ7NZEVS12079</b>	Versionname:	<b>ALHAMBRA Ecom.Style</b>
First Registrationdate:	<b>7/01/2014</b>	Fiscalpower:	<b>DPF 136PK</b>
Expertise Mileage:	<b>159613</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>1532</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/60/16/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 4 mm</b>	Re.R.	<b>Uniroyal: 4 mm</b>

## Assistance equipment

Total cost ex VAT	3389,33
Sliding door L, Bump(s) and scratch(es), LI - Repair and paint (complete)	522,85




Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)

348,09



Seat cover R R, Stain, Acceptable

0,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16




Door panel F R, Scratch(es), Smart repair

110,64



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

362,02



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Dashboard, Scratch(es), Smart repair 110,64



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Sliding door R, Scratch(es), LI - Repair and paint (complete) 522,85

