



VOLKSWAGEN Golf: 1HUE880			
Vinnnumber:	WVWZZZAUZFP548157	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	3/10/2014	Fiscalpower:	
Expertise Mileage:	148919	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1716
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment	
Emergency spare wheel	Yes

Total cost ex VAT	1235,54
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

Wing F R, Bump(s), LI - Repair and paint (complete) 220,18



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Bump(s), LI - Repair and paint (complete) 301,68



Interior, Dirty, Cleaning 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80

