



## VOLKSWAGEN Sharan: 1FCJ170

Vinnumber:	<b>WVWZZZ7NZDV037884</b>	Versionname:	<b>Trendline BMT 115PK</b>
First Registrationdate:	<b>23/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>185427</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>2310</b>
Maintenance:	<b>DEPUIS 1400 KM OU 18 JOURS</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	
Level control		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/60/16/96 H Steel</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

## Assistance equipment

Runflat **No**

Total cost ex VAT	<b>1102,68</b>
Door moulding Lower R R, Scratch(es), Smart repair	<b>0,00</b>



Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>494,68</b>
---	---------------



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Tires, Not original part, P - Check 0,00



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Maintenance, Maintenance, Execute 0,00



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 438,56



Sliding door L, Bump(s), Acceptable 0,00

No pictures to display