

VOLVO XC60: 1EBZ347

Vinnumber:	YV1DZ31A1D2406956	Versionname:	XC60 D3 Kinetic Start/Stop 136PK
First Registrationdate:	16/10/2012	Fiscalpower:	
Expertise Mileage:	217171	Power Kw:	100
Bodytype:	SUV	Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1104
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Sun Roof electric	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


235/60/18/103 V LightMetal				
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 3 mm	Re.R.	Pirelli: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	160,64
-------------------	--------

Front bumper, Damaged, LI - Repair and paint (complete)	0,00
---	------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Wing R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Bump(s), Smart repair		110,64
Wing F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R R, Bump(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Interior, Dirty, Chemical cleaning		50,00
Bumper R, Scratch(es), LI - Repair and paint (complete)		0,00
Alloy rim F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		