



| VOLVO V60: 1ET043       |                          |              |                             |
|-------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber:             | <b>YV1FW84A1D1133087</b> | Versionname: | <b>V60 D2 Kinetic St/St</b> |
| First Registrationdate: | <b>18/03/2013</b>        | Fiscalpower: | <b>115PK</b>                |
| Expertise Mileage:      | <b>107014</b>            | Power Kw:    | <b>84</b>                   |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Black</b>                |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>              |
| Transmission:           |                          | Rims summer: | <b>Aluminium</b>            |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                   |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>1613</b>                 |
| Number of doors:        | <b>5</b>                 |              |                             |
| Number of seats:        | <b>5</b>                 |              |                             |
| Number head rests:      | <b>5</b>                 |              |                             |
| Rims summer:            | <b>Aluminium</b>         |              |                             |
| Category:               | <b>Passenger Car</b>     |              |                             |
| Oil level:              | <b>OK</b>                |              |                             |

| Options                        |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                                  |                       |       |                       |
|----------------|----------------------------------|-----------------------|-------|-----------------------|
| Summer tyres:  | <b>235/45/17/97 W LightMetal</b> |                       |       |                       |
|                | Fr.L.                            | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|                | Re.L.                            | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

| Assistance equipment                                    |            |            |               |
|---|------------|------------|---------------|
| Repair kit  | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                                       |            |            | <b>718,38</b> |
| Alloy rim R L, Scratch(es), Acceptable                  |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>                           |            |            |               |
| Wing R R, Scratch(es), LI - Repair and paint (complete) |            |            | <b>308,20</b> |



|  |              |
|--|--------------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | <b>95,00</b> |
|--|--------------|



Interior, Dirty, Cleaning 0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18

