



VOLKSWAGEN Golf: 1FIQ868			
Vinnumber:	WVWZZZ1KZDM691506	Versionname:	GOLF BRE Trendline BlueMot.DPF 105PK
First Registrationdate:	9/07/2013	Fiscalpower:	
Expertise Mileage:	168347	Power Kw:	77
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2117
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar removable
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	306,80
Wing F R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bad repair, Acceptable	0,00



Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Front bumper, Bump(s), LI - Repair and paint (complete)	211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--------------------------------------------------------------	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display