



VOLVO V60: 1FXK513

Vinnnumber:	YV1FW8481E1180329	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	27/11/2013	Fiscalpower:	
Expertise Mileage:	172982	Power Kw:	84
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3601
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	548,38
-------------------	---------------

Headlight R, Broken, E - Replace	0,00
----------------------------------	-------------



Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
---	---------------



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), E - Replace 235,20



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 63,00



Seat cover R R, Stain, Acceptable 0,00

No pictures to display

Mirror side blinker R, Broken, E - Replace 30,00



Front bumper, Accident, Le - Replace and paint 0,00



Wing F R, Accident, Le - Replace and paint 0,00

