


BMW 3: 1GUH001

Vinnumber:	WBA3J31090F813373	Versionname:	3 BER 318dX 143PK
First Registrationdate:	2/05/2014	Fiscalpower:	
Expertise Mileage:	71909	Power Kw:	105
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3621
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Rear parking sensors
GPS storage	HD	
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/91 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1036,68
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Sill outer L, Scratch(es), LI - Repair and paint (complete)	310,50
---	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Interior, Smell, Ozone treatment	152,58
----------------------------------	--------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display