



AUDI A1 SPORTBACK: 1KNU971

Vinnumber:	WAUZZZ8X7FB039925	Versionname:	1.4 TDI ULTRA 66KW
First Registrationdate:	4/06/2015	Fiscalpower:	
Expertise Mileage:	19936	Power Kw:	66
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2233
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/60/15/84 H LightMetal			
Summer tyres:	Fr.L.	Dunlop: 7 mm	Fr.R.	Dunlop: 7 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	380,00
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)	169,44
-------------------------------------------------------------	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

