



AUDI A6: 1GUH324

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber: | WAUZZZ4G0EN147581 | Versionname: | A6 AVANT Multitr.163PK |
| First Registrationdate: | 2/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 48851 | Power Kw: | 120 |
| Bodytype: | Break | Body color: | Silver |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Maintenance: | OK | Parking lot: | 3806 |
| Battery functioning: | Yes | | |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | |
|--------------------------------|------------------------------|-----------------------|
| Radio CD | | Central consol F |
| GPS storage | HD | Luggage cover |
| GPS storage | | Front parking sensors |
| Windows electric F | | Rear parking sensors |
| Windows electric R | | |
| Cruise Control | | |
| Steering wheel multifunctional | | |
| Seats F heated | | |
| Radio multimedia | | |
| Type of headlighting | Headlighting Xenon | |
| Type of GPS | GPS big screen color | |
| Type of Lining | Lining leather | |
| Type of climate control | Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
| | 245/45/18/100 V LightMetal | | | |
| Winter tyres: | Fr.L. | Michelin: 7 mm | Fr.R. | Michelin: 7 mm |
| | Re.L. | Michelin: 7 mm | Re.R. | Michelin: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-------------------|---------------|
| Total cost ex VAT | 285,00 |
|-------------------|---------------|

| | |
|--|--------------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|--------------|





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00

