



BMW 1 HATCH: 1JUL991			
Vinnumber:	WBA1C910X0P991632	Versionname:	1.6 116D
First Registrationdate:	27/02/2015		EFFICIENTDYNAMICS
Expertise Mileage:	110738		EDIT. (85KW)
Bodytype:		Fiscalpower:	
Gearbox:	MAN 6 VIT	Power Kw:	85
Transmission:	Back	Body color	Blue
Fueltype:	Diesel	Paint type	Metalic
Maintenance	OK	Rims summer	Aluminium
Battery functioning	Yes	Oil level	OK
Number of doors	5	Parking lot	3104
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage			
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Winter tyres:	205/55/16/92 MS LightMetal		
	Fr.L.	Michelin: 4 mm	Fr.R.
	Re.L.	Michelin: 4 mm	Re.R.
		Michelin: 4 mm	Michelin: 4 mm
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1100,50
Bumper R, Scratch(es), LI - Repair and paint (complete)			223,80
			
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)			308,20



Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

GPS, Crack, E - Replace	0,00
-------------------------	------



Windscreen, Stone chip(s), Windscreen repair	0,00
--	------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Interior, Dirty, Cleaning	100,00
---------------------------	--------



Sill outer R, Bump(s), LI - Repair and paint (complete)	310,50
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

