



AUDI A6: 1KRD773

Vinnumber:	WAUZZZ4G2FN088504	Versionname:	2.0 TDI ULTRA 100KW
First Registrationdate:	15/06/2015	Fiscalpower:	
Expertise Mileage:	120017	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3225
Maintenance	1 LITER OLIE BIJVULLEN		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/60/16/98 HA LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 2 mm	Fr.R.	Uniroyal: 2 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	137,99
-------------------	---------------

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Double pedal, Not functioning (well), Repair/replace (lump sum)	0,00
---	-------------



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s), PDR - Knock out without painting 82,80



Rearlight R tailgate, Scratch(es), 67 - Polish 55,19

