



CITROEN C5: 1GTK337

Vinnumber:	VF7RWRHR8EL505251	Versionname:	C5 TOURER Business GPS
First Registrationdate:	24/04/2014	Fiscalpower:	FAP 136PK
Expertise Mileage:	63827	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3715
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/92 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2350,27
-------------------	----------------

Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	---------------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Wing F R, Damaged, LI - Repair and paint (complete) 220,18



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Aerial, Damaged, E - Replace 15,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof, Scratch(es), LI - Repair and paint (complete) 481,50



Supplementary brake lights, Crack, E - Replace 36,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------

