


**FORD Focus: 1FRF542**

Vinnumber:	<b>WF0LXXGCBLDC67441</b>	Versionname:	<b>FOCUS CLIP. EConetic Titanium 88g 105PK</b>
First Registrationdate:	<b>1/10/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>137688</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Brown</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>2710</b>
Maintenance:	<b>GEDAAN OP 127170 KM</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F
GPS storage	<b>SD</b> Rear parking sensors
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H Steel</b>			
Summer tyres:	Fr.L.	<b>Semperit: 4 mm</b>	Fr.R.	<b>Semperit: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------


















**Total cost ex VAT** 1600,20

**Bumper R, Scratch(es), Acceptable** 0,00

*No pictures to display*
**Wing R R, Scratch(es), LI - Repair and paint (complete)** 308,20

**Windscreen, Stone chip(s), Acceptable** 0,00

*No pictures to display*

Bonnet, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearlight L, Broken, E - Replace	114,00
 	
Wheel cover F R, Scratch(es), E - Replace	30,00
 	
Roof, Scratch(es), LI - Repair and paint (complete)	481,50
 	
Door F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), PDR - Knock out without painting	63,00
  	
Wheel cover R L, Scratch(es), E - Replace	30,00
 	
Wing F L, Bump(s), LI - Repair and paint (complete)	220,18
 	
Seat cover F L, Hole, Smart repair	64,32
 	
Luggage space cover, Missing, E - Replace	240,00
 	
Interior, Dirty, Acceptable	0,00
<i>No pictures to display</i>	
Foglight L, Incomplete, E - Replace	49,00
