


BMW 4 Gran Coupe: XC8689

Vinnumber:	WBA4B51000D418765	Versionname:	4 GRAN COUPE 420d
First Registrationdate:	22/10/2014	Fiscalpower:	184PK
Expertise Mileage:	119765	Power Kw:	135
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3114
Battery functioning	Yes		
Number of doors	5		
Number of seats	4		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage		Front parking sensors
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	644,72
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	278,16



Bumper F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Foglight R, Crack, E - Replace	156,00



Wing R R, Scratch(es), It - Spot repair	115,56
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

