



FIAT DOBLO II: 1NBZ453

Vinnnumber:	ZFA26300006B38365	Versionname:	
First Registrationdate:	15/01/2016	Fiscalpower:	
Expertise Mileage:	53124	Power Kw:	66
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV30
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F		Rear parking sensors	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/92 T Steel			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	705,13
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15



Interior, Dirty, Cleaning	0,00
---------------------------	------



Ignition key, Missing, E - Replace 150,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 158,85

No pictures to display

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 165,13



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display