



BMW 5: 1EJR631

Vinnumber:	WBAMX11030DY10813	Versionname:	5 TOURING 520dA Start/Stop 163PK aut
First Registrationdate:	1/01/2013	Fiscalpower:	
Expertise Mileage:	178883	Power Kw:	120
Bodytype:		Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3205
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/92 H LightMetal			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 4 mm	Re.R.	Kleber: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			463,65
Sill outer R, Scratch(es), It - Spot repair			115,56



Rear window, Scratch(es), Acceptable		0,00
--------------------------------------	--	-------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	348,09
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Bad repair, Acceptable	0,00
----------------------------------	------

