




BMW 2: CH8742			
Vinnumber:	WBA1J710X0VX31155	Versionname:	2 M COUPE M235i 326PK
First Registrationdate:	25/04/2014	Fiscalpower:	
Expertise Mileage:	139701	Power Kw:	240
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4728
Number of doors:	2		
Number of seats:	4		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	HD Front parking sensors
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Sport seats	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
245/35/18/92 Y LightMetal				
Summer tyres:	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			953,80
Wing R L, Bump(s), LI - Repair and paint (complete)			332,20



Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------




Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, LI - Repair and paint (complete) 259,80



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 235,80



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Scratch(es), Acceptable 0,00

No pictures to display