



CITRO?N C4 Picasso: 1ENE918

Vinnnumber:	VF7UD9HR8DJ511373	Versionname:	C4 PICASSO Bus.GPS FAP
First Registrationdate:	29/01/2013	Fiscalpower:	112PK
Expertise Mileage:	103894	Power Kw:	82
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1106
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Jack **Yes**

Total cost ex VAT **617,30**

Bonnet, Bump(s) and scratch(es), Acceptable **0,00**

No pictures to display

Sill outer R, Bump(s), LI - Repair and paint (complete) **310,50**



Headlight R, Scratch(es), Acceptable **0,00**

No pictures to display

Bumper R, Scratch(es), Acceptable **0,00**

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) **211,80**



Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00

