


**FORD Focus: 1EDI086**

|                         |                          |              |  |
|-------------------------|--------------------------|--------------|--|
| Vinnnumber:             | <b>WF0LXXGCBLCY56887</b> | Versionname: | <b>FOCUS CLIP. ECONetic Titanium 88g 105PK</b> |
| First Registrationdate: | <b>26/10/2012</b>        | Fiscalpower: |  |
| Expertise Mileage:      | <b>113417</b>            | Power Kw:    | <b>77</b>                                      |
| Bodytype:               | <b>Break</b>             | Body color:  | <b>Orange</b>                                  |
| Gearbox:                | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                                 |
| Transmission:           |                          | Rims summer: | <b>Steel</b>                                   |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                                      |
| Battery functioning:    | <b>Yes</b>               | Parking lot: | <b>1715</b>                                    |
| Number of doors:        | <b>5</b>                 |              |  |
| Number of seats:        | <b>5</b>                 |              |  |
| Number head rests:      | <b>5</b>                 |              |  |
| Rims summer:            | <b>Steel</b>             |              |  |
| Category:               | <b>Passenger Car</b>     |              |  |
| Oil level:              | <b>OK</b>                |              |  |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Central consol F             |
| Windows electric F             | Luggage cover                |
| Windows electric R             | Rear parking sensors         |
| Cruise Control                 |                              |
| Steering wheel multifunctional |                              |
| Seats F heated                 |                              |
| Radio multimedia               |                              |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of GPS                    | <b>GPS big screen color</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                             |                          |       |                          |
|---------------|-----------------------------|--------------------------|-------|--------------------------|
|               | <b>215/55/16/93 H Steel</b> |                          |       |                          |
| Summer tyres: | Fr.L.                       | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|               | Re.L.                       | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

**Assistance equipment**

|                       |            |
|-----------------------|------------|
| Emergency spare wheel | <b>Yes</b> |
|-----------------------|------------|

|   |        |
|---|--------|
| Total cost ex VAT   | 776,55 |
| Door R R, Bump(s), Acceptable                                       | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |





|                           |      |
|---------------------------|------|
| Interior, Dirty, Cleaning | 0,00 |
|---------------------------|------|



|                                    |        |
|------------------------------------|--------|
| Ignition key, Damaged, E - Replace | 150,00 |
|------------------------------------|--------|



|   |        |
|---|--------|
| Door R L, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---|--------|



|                                       |      |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display