


**FIAT 500L: 1FCT493**

|                         |                          |              |                         |
|-------------------------|--------------------------|--------------|-------------------------|
| Vinnnumber:             | <b>ZFA19900005049465</b> | Versionname: | <b>500L Lounge 83PK</b> |
| First Registrationdate: | <b>27/05/2013</b>        | Fiscalpower: |                         |
| Expertise Mileage:      | <b>64475</b>             | Power Kw:    | <b>61</b>               |
| Bodytype:               |                          | Body color:  | <b>Red</b>              |
| Gearbox:                | <b>MAN 5 VIT</b>         | Paint type:  | <b>Metalic</b>          |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Aluminium</b>        |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>               |
| Maintenance:            | <b>OK</b>                | Parking lot: | <b>3223</b>             |
| Battery functioning:    | <b>Yes</b>               |              |                         |
| Number of doors:        | <b>5</b>                 |              |                         |
| Number of seats:        | <b>5</b>                 |              |                         |
| Number head rests:      | <b>5</b>                 |              |                         |
| Rims summer:            | <b>Aluminium</b>         |              |                         |
| Category:               | <b>Passenger Car</b>     |              |                         |
| Oil level:              | <b>OK</b>                |              |                         |

**Options**

|                                |                              |
|--------------------------------|------------------------------|
| Radio CD                       | Sun Roof electric            |
| Windows electric F             | Panoramic roof               |
| Windows electric R             | Central consol F             |
| Cruise Control                 | Luggage cover                |
| Steering wheel multifunctional | Rear parking sensors         |
| Type of headlighting           | <b>Headlighting Halogen</b>  |
| Type of Lining                 | <b>Lining fabrics</b>        |
| Type of climate control        | <b>Autom climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                          |       |                          |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
|               | <b>205/55/16/94 H LightMetal</b> |                          |       |                          |
| Summer tyres: | Fr.L.                            | <b>Continental: 4 mm</b> | Fr.R. | <b>Continental: 4 mm</b> |
|               | Re.L.                            | <b>Continental: 4 mm</b> | Re.R. | <b>Continental: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                   |         |
|-------------------|---------|
| Total cost ex VAT | 1932,16 |
|-------------------|---------|























|  |        |
|--|--------|
| Rearview mirror R complete, Scratch(es), E - Replace | 168,00 |
|--|--------|



|   |        |
|---|--------|
| Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 356,20 |
|---|--------|



|                                     |        |
|-------------------------------------|--------|
| Alloy rim F R, Damaged, E - Replace | 235,20 |
|-------------------------------------|--------|

|   |   |  |        |
|---|---|--|--------|
|     |     |     |        |
| Rear spoiler, Scratch(es), LI - Repair and paint (complete)                         |   |  | 115,56 |
|    |    |  |        |
| Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)                 |   |  | 301,68 |
|    |    |    |        |
|    |   |  |        |
| Maintenance book, Missing, E - Replace  |   |  | 0,00   |
| <i>No pictures to display</i>   |   |  |        |
| Door F R, Bump(s), PDR - Knock out without painting                                 |   |  | 63,00  |
|   |   |  |        |
| Door frame F R, Bump(s) and scratch(es), It - Spot repair                           |   |  | 115,56 |
|  |  |  |        |
| Bumper F L, Scratch(es), It - Spot repair   |   |  | 115,56 |
|  |  |  |        |
|  |   |  |        |
| Door panel R L, Scratch(es), Smart repair   |   |  | 110,64 |
|  |  |  |        |
| Sill outer L, Bump(s), It - Spot repair   |   |  | 115,56 |
|  |  |  |        |
| Alloy rim F L, Damaged, E - Replace   |   |  | 235,20 |



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00

