



| | | | |
|------------------------------------|--------------------------|--------------|---------------------------------|
| BMW 5 TOURING: 1LCE770 | | | |
| Vinnumber: | WBA5L31060G120032 | Versionname: | 2.0 520D (120KW) TOURING |
| First Registrationdate: | 18/08/2015 | Fiscalpower: | |
| Expertise Mileage: | 59493 | Power Kw: | 120 |
| Bodytype: | Break | Body color: | White |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3624 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | |
|--------------------------------|------------------------------|
| Options | |
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Front parking sensors |
| Cruise Control | Rear parking sensors |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |
| Sport seats | |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|----------------------------------|----------------------|-------|----------------------|
| Degree of wear | | | | |
| | 245/45/19/96 Y LightMetal | | | |
| Summer tyres: | Fr.L. | Pirelli: 5 mm | Fr.R. | Pirelli: 5 mm |
| | Re.L. | Pirelli: 5 mm | Re.R. | Pirelli: 5 mm |

| | |
|---------------------------------------------------------------------|---------------|
| Assistance equipment | |
| Runflat | Yes |
| Total cost ex VAT | 190,00 |
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|----------------------------------------------------------|-------------|
| Front bumper, Bump(s) and scratch(es), Acceptable | 0,00 |
|----------------------------------------------------------|-------------|

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display