


BMW 4 GRAN COUPE: BB1976

Vinnumber:	WBA4F110X0D939361	Versionname:	2.0 420D XDRIVE (140KW) 4WD GRAN COUPE
First Registrationdate:	12/04/2016	Fiscalpower:	
Expertise Mileage:	81789	Power Kw:	140
Bodytype:		Body color:	Silver
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 21000 KM	Parking lot:	4611
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/18/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

 Runflat **Yes**

Total cost ex VAT	380,00
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00


 Tailgate, Scratch(es), Acceptable **0,00**

No pictures to display

 Bonnet, Scratch(es), Acceptable **0,00**

No pictures to display

 Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) **95,00**



Alloy rim R R polished, Damaged, LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00

