



MERCEDES CLA: 1GMB806			
Vinnnumber:	WDD1173011N079584	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	7/03/2014	Fiscalpower:	
Expertise Mileage:	91435	Power Kw:	100
Bodytype:		Body color:	Light Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1707
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/40/18/92 V LightMetal			
Summer tyres:	Fr.L.	Kleber: 4 mm	Fr.R.	Kleber: 4 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment			
Repair kit	No	Compressor	No
Total cost ex VAT			435,00
Alloy rim F L polished, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)			95,00





Tyre repair kit, Missing, E - Replace	150,00
---------------------------------------	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

