


PEUGEOT Partner: 1GSS359

Vinnnumber:	VF37J9HN0EJ625626	Versionname:	PARTNER TEPEE 2PLC Active 75PK
First Registrationdate:	1/01/2020	Fiscalpower:	
Expertise Mileage:	91367	Power Kw:	55
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4103
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/15/94 V Steel				
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2324,10
Bumper R, Bump(s), Smart repair	110,64



Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	158,85
---	--------



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Luggage space cover, Missing, E - Replace 180,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 165,13



Interior, Dirty, Cleaning 100,00



Registration Document, Missing, E - Replace 150,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 158,85



Roof, Bump(s), Acceptable 0,00

No pictures to display

Tailgate, Bump(s) and scratch(es), Le - Replace and paint 799,99



Front bumper, Scratch(es), Smart repair 110,64



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

231,15

