



PEUGEOT 5008: 1FBJ777

Vinnnumber:	VF30E9HD8DS070155	Versionname:	5008 e-HDi Allure FAP BMP 115PK Aut.
First Registrationdate:	15/05/2013	Fiscalpower:	
Expertise Mileage:	140105	Power Kw:	84
Bodytype:	MPV	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1205
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting:	Headlighting Halogen	Type of Tow bar:	Tow bar removable
Type of GPS:	GPS big screen color		
Type of Lining:	Lining leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 V LightMetal			
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Total cost ex VAT	1774,29
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Maintenance book, Missing, E - Replace 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Trunk lid covering R, Scratch(es), Smart repair 110,64



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

