



MERCEDES C: 1FQL847			
Vinnnumber:	WDD2040001A906577	Versionname:	C BER 180 CDI BlueEFF. S&S 120PK
First Registrationdate:	24/09/2013	Fiscalpower:	
Expertise Mileage:	122867	Power Kw:	88
Bodytype:	Berline	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2229
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
GPS storage	HD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		








Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			693,30
Wing R L, Bump(s), Acceptable			0,00
<i>No pictures to display</i>			
Mirror side blinker L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Roof, Chemical polution, LI - Repair and paint (complete)			481,50



Alloy rim F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80

		
Wing R R, Bump(s), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Bad repair, Paint		0,00
		
		
Door F R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Repaired, Acceptable		0,00
<i>No pictures to display</i>		