



MERCEDES CLS: 1JRU292

Vinnnumber:	WDD2183011A146917	Versionname:	CLS 220 BlueTEC 170PK Aut.
First Registrationdate:	10/02/2015	Fiscalpower:	
Expertise Mileage:	191759	Power Kw:	120
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2401
Maintenance:	SERV B 13700 KM		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Seats electric F R
GPS storage	SD
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunction	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/17/99 H LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	4111,19
--------------------------	----------------

Sill outer L, Scratch(es), LI - Repair and paint (complete)	372,60
--	---------------



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	348,09
--	---------------



Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84



Front bumper, Bump(s) and scratch(es), Le - Replace and paint

862,80



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

382,02



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

382,02



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

369,84



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper grille F R, Scratch(es), E - Replace 34,08



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Armrest R M, Damaged, Smart repair 112,32

