



<b>RENAULT Clio: 1GVY008</b>			
Vinnumber:	<b>VF15RJL0H50895014</b>	Versionname:	<b>CLIO IV BER e-Expression St&amp;St 90PK</b>
First Registrationdate:	<b>15/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>70824</b>	Power Kw:	<b>66</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4820</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>	
GPS storage	<b>HD Luggage cover</b>
GPS storage	
Windows electric F	
Cruise Control	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>185/65/15/88 T Steel</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 6 mm</b>	Fr.R.	<b>Bridgestone: 6 mm</b>
	Re.L.	<b>Bridgestone: 6 mm</b>	Re.R.	<b>Bridgestone: 6 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

Total cost ex VAT	<b>761,46</b>
Wheel cover F L, Scratch(es), E - Replace	<b>24,00</b>



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>169,44</b>
---	---------------





Door R R, Scratch(es), LI - Repair and paint (complete)	254,68
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Door F R, Repaired, Acceptable	0,00
--------------------------------	------

*No pictures to display*

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Wheel cover R L, Scratch(es), E - Replace	24,00
---	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace	24,00
---	-------



Tailgate, Scratch(es), LI - Repair and paint (complete)	241,34
---	--------



Dashboard, Scratch(es), Acceptable	0,00
------------------------------------	------

*No pictures to display*

Wheel cover R R, Scratch(es), E - Replace	24,00
---	-------

