



| | | | |
|------------------------------------|--------------------------|--------------|--|
| RENAULT Clio: 1GVZ671 | | | |
| Vinnnumber: | VF15RJL0H50895021 | Versionname: | CLIO IV BER e-Expression St&St 90PK |
| First Registrationdate: | 15/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 94831 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Light Grey |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 4811 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 4 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

| | |
|--------------------------------|-------------------------------|
| Options | |
| Windows electric F | Luggage cover |
| Cruise Control | |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of GPS: | GPS big screen color |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

| | | | |
|-------------------------------------|-----------|---------------------|------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|-----------------------------|--------------------------|-------|--------------------------|
| Degree of wear | | | | |
| | 185/65/15/88 T Steel | | | |
| Summer tyres: | Fr.L. | Bridgestone: 5 mm | Fr.R. | Bridgestone: 5 mm |
| | Re.L. | Bridgestone: 4 mm | Re.R. | Bridgestone: 4 mm |

| | |
|-----------------------------|------------|
| Assistance equipment | |
| Repair kit | Yes |
| Compressor | No |

| | |
|---|---------------|
| Total cost ex VAT | 264,42 |
| Bumper corner R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover R R, Not original part, E - Replace | 24,00 |



| | |
|---|--------------|
| Wheel cover R L, Not original part, E - Replace | 24,00 |
|---|--------------|



| | |
|---------------------------------------|--------|
| Tyre repair kit, Missing, E - Replace | 168,42 |
|---------------------------------------|--------|

No pictures to display

| | |
|---------------------------|------|
| Interior, Dirty, Cleaning | 0,00 |
|---------------------------|------|



| | |
|---|-------|
| Wheel cover F R, Not original part, E - Replace | 24,00 |
|---|-------|



| | |
|---|-------|
| Wheel cover F L, Not original part, E - Replace | 24,00 |
|---|-------|

