


RENAULT Megane: 1EVU221

Vinnumber:	VF1KZ140648787048	Versionname:	MEGANE GT Energy Dynamique 110PK
First Registrationdate:	3/04/2013	Fiscalpower:	
Expertise Mileage:	80451	Power Kw:	81
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3103
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Sun Roof electric	
Windows electric F	Panoramic roof	
Windows electric R	Central consol F	
Cruise Control	Luggage cover	
Steering wheel multifunction	Rear parking sensors	
Alarm	Type of Tow bar	Tow bar removable
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2896,10
Front bumper, Scratch(es), Acceptable	0,00


No pictures to display

Roof, Hail damage, PDR - Hail	550,00
-------------------------------	--------





Bumper R, Bump(s) and scratch(es), It - Spot repair 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Roof pillar L, Hail damage, PDR - Hail 150,00



Dashboard, Scratch(es), Smart repair 110,64



Rear spoiler, Hail damage, PDR - Hail 150,00



Wing R L, Hail damage, PDR - Hail 100,00




Roof pillar L, Hail damage, PDR - Hail 125,00






Door R L, Hail damage, PDR - Hail 75,00



Door R L, Hail damage, PDR - Hail 100,00



Bonnet, Bump(s), Le - Replace and paint 1016,70



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

