


**OPEL Zafira: 1DRK624**

Vinnumber:	<b>WOLPE9EM7C2115895</b>	Versionname:	<b>ZAFIRA TOURER ecoFL.Cosmo St/St.130PK</b>
First Registrationdate:	<b>1/08/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>190690</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4426</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>SD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar removable</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/50/17/94 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	211,80
-------------------	--------

Rocker panel inner F L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Door frame F R, Bump(s), Acceptable	0,00
-------------------------------------	------

*No pictures to display*

Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

*No pictures to display*

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

*No pictures to display*

Door F L, Repaired, Acceptable	0,00
--------------------------------	------

*No pictures to display*

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Rocker panel inner R R, Scratch(es), Acceptable

0,00

*No pictures to display*