


RENAULT Grand Espace: 1FWW165

Vinnumber:	VF1JKFHC649942083	Versionname:	GR.ESPACE Alcantara
First Registrationdate:	21/11/2013	Fiscalpower:	130PK
Expertise Mileage:	122582	Power Kw:	96
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1305
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage	SD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	491,44
-------------------	--------

Bumper Trim F, Scratch(es), E - Replace	0,00
---	------



Ignition key, Damaged, Acceptable	0,00
-----------------------------------	------

No pictures to display

Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Repaired, Acceptable 0,00



Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Smart repair 110,64



Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rearview mirror R complete, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Repaired, Acceptable 0,00

