


**RENAULT Espace: 1FCO205**

Vinnnumber:	<b>VF1JKFJAC49070185</b>	Versionname:	<b>ESPACE Alcantara 149PK Aut.</b>
First Registrationdate:	<b>24/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>156781</b>	Power Kw:	<b>110</b>
Bodytype:		Body color	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3504</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather and alcantara</b>
Type of climate control	<b>Autom climate control</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/101 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Total cost ex VAT	1086,08
Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	369,84



Door R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Grill frame, Scratch(es), E - Replace	74,00



Alloy rim F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Rear bulkhead lining, Scratch(es), Smart repair 110,64



Door R L, Bump(s) and scratch(es), Acceptable 0,00

*No pictures to display*

Alloy rim R R, Damaged, E - Replace 277,44



Bonnet, Stone chip(s), Acceptable 0,00

*No pictures to display*