



VOLKSWAGEN Golf: 1HCG167

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WVWZZZAUZEW400311 | Versionname: | GOLF BER Trendline 90PK |
| First Registrationdate: | 17/06/2014 | Fiscalpower: | |
| Expertise Mileage: | 94267 | Power Kw: | 66 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1410 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|------------------------------|-----------------------|--|
| Radio CD | | Luggage cover | |
| Windows electric F | | Front parking sensors | |
| Cruise Control | | Rear parking sensors | |
| Steering wheel multifunctional | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |
| Adaptive cruise control | | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
| | 195/65/15/91 T Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 4 mm | Fr.R. | Michelin: 4 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|-------------------|--------|
| Total cost ex VAT | 598,28 |
|-------------------|--------|

| | |
|---|--------|
| Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) | 290,08 |
|---|--------|



| | |
|---|------|
| Door R R, Bump(s) and scratch(es), Acceptable | 0,00 |
|---|------|

No pictures to display

| | |
|---------------------------------------|------|
| Front bumper, Scratch(es), Acceptable | 0,00 |
|---------------------------------------|------|

No pictures to display

| | |
|---|--------|
| Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) | 308,20 |
|---|--------|

