



RENAULT Scenic: 1EUU600			
Vinnnumber:	VF1JZ140648624239	Versionname:	SCENIC Energ.Privilège 110PK
First Registrationdate:	26/03/2013	Fiscalpower:	
Expertise Mileage:	121651	Power Kw:	81
Bodytype:	Hatchback	Body color	Burgundy
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3224
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather and alcantara
Type of climate control	Autom climate control




Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/95 V LightMetal			
Summer tyres:	Fr.L.	Semperit: 5 mm	Fr.R.	Semperit: 5 mm
	Re.L.	Semperit: 4 mm	Re.R.	Semperit: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			494,98
Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)			0,00



Bumper R, Scratch(es), Acceptable	0,00
--	-------------

Bonnet, Chemical polution, LI - Repair and paint (complete)	0,00
	
Wing R L, Bump(s), PDR - Knock out without painting	63,00
	
Roof, Chemical polution, Acceptable	0,00
No pictures to display	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
