



**TOYOTA AYGO: YX7377**

Vinnumber:	<b>JTDKGNEC80N216721</b>	Versionname:	<b>1.0 VVT-I X-PLAY MMT</b>
First Registrationdate:	<b>12/01/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>16749</b>	Power Kw:	<b>51</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>4120</b>
Number of doors	<b>4</b>		
Number of seats	<b>4</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

**Options**

GPS storage	<b>HD</b>	Luggage cover
GPS storage		
Windows electric F		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>165/60/15/77 T Steel</b>			
Winter tyres:	Fr.L.	<b>Continental: 7 mm</b>	Fr.R.	<b>Continental: 7 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**


Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>468,58</b>
-------------------	---------------

Roof, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------







Wheel cover F L, Scratch(es), E - Replace	<b>24,00</b>
---	--------------



Door F L, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Seat cover R R, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s), LI - Repair and paint (complete)	176,14
	
Wheel cover F R, Scratch(es), E - Replace	24,00
	
Aerial, Missing, E - Replace	12,00
	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
	
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	