



TOYOTA AURIS: 1NLY608			
Vinnumber:	<b>SB1MS3JE60E233847</b>	Versionname:	<b>1.8 HYBRID LOUNGE CVT AUTO</b>
First Registrationdate:	<b>22/03/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>22103</b>	Power Kw:	<b>73</b>
Bodytype:		Body color	<b>Red</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3203</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-leather</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
Summer tyres:	<b>225/45/17/91 W LightMetal</b>			
	Fr.L.	<b>Dunlop: 7 mm</b>	Fr.R.	<b>Dunlop: 7 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>544,50</b>
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)			<b>310,50</b>



Alloy rim R R polished, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		<b>0,00</b>
<i>No pictures to display</i>		
Door panel R L, Scratch(es), E - Replace		<b>114,00</b>



Seat cover R R, Stain, Cleaning	25,00
---------------------------------	-------



Rocker panel inner R R, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

*No pictures to display*

Wing R L, Repaired, P - Check	0,00
-------------------------------	------

