



## SKODA Octavia: 1GSB904

Vinnnumber:	<b>TMBAG7NE2D0019037</b>	Versionname:	<b>OCTAVIA BER Ambition</b>
First Registrationdate:	<b>14/04/2014</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>148552</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OLIE BIJVULLEN</b>	Parking lot:	<b>1109</b>
Maintenance:	<b>NOT OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of GPS:	<b>GPS big screen color</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1313,86</b>
-------------------	----------------

Bumper R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

No pictures to display

Door F R, Scratch(es), LI - Repair and paint (complete)	<b>318,35</b>
---	---------------





Tailgate, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Headlight R, Not functioning (well), E - Replace 0,00



Seat cover R, Stain, Cleaning 25,00



Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18



Windscreen, Stone chip(s), Windscreen repair 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), E - Replace 0,00

No pictures to display