



VOLKSWAGEN Passat: 1GSC144			
Vinnnumber:	WVWZZZ3CZEE133400	Versionname:	PASSAT VAR Comfortline BMT 105PK
First Registrationdate:	14/04/2014	Fiscalpower:	
Expertise Mileage:	174752	Power Kw:	77
Bodytype:	Break	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1331
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	215/55/16/97 Y LightMetal			
	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment	
Spare wheel	Yes

Total cost ex VAT	757,68
Bumper grille, Damaged, E - Replace	32,40



Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Door R R, Bump(s), Acceptable

0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete)

211,80



Door F L, Scratch(es), Acceptable

0,00

No pictures to display