



VOLKSWAGEN Passat: 1FRF550

Vinnnumber:	WVWZZZ3CZEE047587	Versionname:	PASSAT VAR Trendline BM
First Registrationdate:	1/10/2013	Fiscalpower:	105PK
Expertise Mileage:	112421	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2602
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	63,00
Door F L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror R complete, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

No pictures to display

Door R L, Bump(s), Acceptable	0,00
--------------------------------------	-------------

No pictures to display

Bonnet, Stone chip(s), Acceptable	0,00
--	-------------

No pictures to display

Windscreen, Repaired, Acceptable	0,00
---	-------------

No pictures to display

Wheel cover F R, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display