



VOLKSWAGEN Golf: 1HAZ245

Vinnnumber:	WVWZZZAUZEW235157	Versionname:	GOLF BER Trendline 90PK
First Registrationdate:	6/06/2014	Fiscalpower:	
Expertise Mileage:	107708	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4322
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	SD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			776,94
Wing R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R L, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Damaged, E - Replace			235,20



Front bumper, Scratch(es), It - Spot repair 115,56



Wing R L, Bump(s), Acceptable 0,00

No pictures to display

Seat cover F L, Stain, Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s), PDR - Knock out without painting 63,00



Door F L, Bump(s), Acceptable 0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 268,18



Rear window, Not original part, Remove lettering 0,00

No pictures to display