


AUDI A3: 1GWN829

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------|
| Vinnnumber: | WAUZZZ8V0EA168639 | Versionname: | A3 SB Ambition 105PK |
| First Registrationdate: | 20/05/2014 | Fiscalpower: | |
| Expertise Mileage: | 144758 | Power Kw: | 77 |
| Bodytype: | Hatchback | Body color: | Black |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2424 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | Rear parking sensors |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 225/45/17/91 W LightMetal | | | |
| Summer tyres: | Fr.L. | Michelin: 3 mm | Fr.R. | Michelin: 3 mm |
| | Re.L. | Michelin: 4 mm | Re.R. | Michelin: 4 mm |

Assistance equipment

| | | | |
|-----------------------|------------|------|------------|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|------------|------|------------|

| | |
|---|--------|
| Total cost ex VAT | 972,80 |
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door R R, Bump(s) and scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) | 307,80 |





Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Covering interior front pillar L, Burned, E - Replace 59,00



Bumper grille, Damaged, E - Replace 64,00



Alloy rim F R, Damaged, E - Replace 235,20



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

