



BMW 1 HATCH: WG6385

Vinnumber:	WBA1S510505A80716	Versionname:	2.0 118D (110KW)
First Registrationdate:	15/05/2015	Fiscalpower:	
Expertise Mileage:	122252	Power Kw:	110
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	2124
Maintenance	-3000KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	115,56
-------------------	---------------

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Rearview mirror housing L, Chemical polution, LI - Repair and paint (complete)	115,56
--	---------------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display