



BMW 3: 1GTQ184			
Vinnumber:	WBA3D11000F329233	Versionname:	3 BER 318d 136PK
First Registrationdate:	25/04/2014	Fiscalpower:	
Expertise Mileage:	100885	Power Kw:	100
Bodytype:		Body color	Light Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3117
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Rear parking sensors
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting LED
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment	
Runflat	Yes

Total cost ex VAT	734,10
Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
-------------------------------------------------------------------------	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

